

Passingtabel inwendige maten

C : Voor inwendige maten volgens ISO 286 deel 2

| nominale maat | | | | | | | | | |
|---------------|--|------|------|------|------|-------|-------|-------|-------|
| boven : | 3 | 6 | 10 | 18 | 30 | 50 | 80 | 120 | |
| tot en met : | 3 | 6 | 10 | 18 | 30 | 50 | 80 | 120 | 180 |
| passing | tolerantievelden in 0,001 mm (μm) | | | | | | | | |
| C13 | +200 | +240 | | | | | | | |
| | +60 | +60 | | | | | | | |
| C14 | +310 | +370 | | | | | | | |
| | +60 | +70 | | | | | | | |
| D9 | +45 | +60 | | | | | | | |
| | +20 | +30 | | | | | | | |
| D10 | +60 | +78 | | | | | | | |
| | +20 | +30 | | | | | | | |
| D11 | +80 | +115 | +130 | | | | | | |
| | +20 | +30 | +40 | | | | | | |
| D12 | +120 | +150 | +190 | +230 | +275 | +330 | +400 | +470 | +545 |
| | +20 | +30 | +40 | +50 | +65 | +80 | +100 | +120 | +145 |
| EF8 | +24 | +28 | +40 | | | | | | |
| | +10 | +14 | +18 | | | | | | |
| E11 | +74 | +95 | +115 | +142 | | | | | |
| | +14 | +20 | +25 | +32 | | | | | |
| E12 | +100 | +140 | +175 | +212 | | | | | |
| | +14 | +20 | +25 | +32 | | | | | |
| F7 | +16 | +22 | +28 | +34 | +41 | +50 | +60 | +71 | +83 |
| | +6 | +10 | +13 | +16 | +20 | +25 | +30 | +36 | +43 |
| H5 | +4 | +5 | +6 | +8 | +9 | +11 | +13 | +15 | +18 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H7 | +10 | +12 | +15 | +18 | +21 | +25 | +30 | +35 | +40 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H8 | +14 | +18 | +22 | +27 | +33 | +39 | +46 | +54 | +63 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H9 | +25 | +30 | +36 | +43 | +52 | +62 | +74 | +87 | +100 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H11 | +60 | +75 | +90 | +110 | +130 | +160 | +190 | +220 | +250 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H12 | +100 | +120 | +150 | +180 | +210 | +250 | +300 | +350 | +400 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H13 | +140 | +180 | +220 | +270 | +330 | +390 | +460 | +540 | +630 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H14 | +250 | +300 | +360 | +430 | +520 | +620 | +740 | +870 | +1000 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| H15 | +400 | +480 | +580 | +700 | +840 | +1000 | +1200 | +1400 | +1600 |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| JS9 | +12,5 | +15 | +18 | | | | | | |
| | -12,5 | -15 | -18 | | | | | | |
| K9 | 0 | 0 | 0 | | | | | | |
| | -25 | -30 | -36 | | | | | | |